

VW Lupo Window Regulator Cog

As you can see in the below picture the motor spindle fits nicely into the motor cog



On the other side of my regulator cog there are a few cogs which has been flattened and I believe this to be the cause of the electric window just clicking and not operating.

VW Lupo Window Regulator Cog

If you look at the picture below, you'll see what I mean about the flattened cogs



VW Lupo Window Regulator Cog

Because of this, you'll see the motor spindle not engaging correctly



VW Lupo Window Regulator Cog

The next two photos are where the parts sit within the motor section

